





For use with: W 61, W 101, W 201

Description and Model		Width A	Order-No. 260°C	Order-No. 310°C	Order-No. 370°C	Order-No. 425°C
For 60 W soldering iron (W61)						
Chisel tip straight 	1,6 mm		CT5A5 5 42 005 99	CT5A6 5 42 006 99	CT5A7 5 42 007 99	CT5A8 5 42 008 99
	2,4 mm		CT5B5 5 42 015 99	CT5B6 5 42 016 99	CT5B7 ① 5 42 017 99	CT5B8 5 42 018 99
	3,2 mm		CT5C5 5 42 025 99	CT5C6 5 42 026 99	CT5C7 5 42 027 99	CT5C8 5 42 028 99
	5,0 mm		CT5D5 5 42 035 99	CT5D6 5 42 036 99	CT5D7 5 42 037 99	CT5D8 5 42 038 99
Chisel tip bent (45°) 	1,6 mm		CT5AX5 5 42 105 99	CT5AX6 5 42 106 99	CT5AX7 5 42 107 99	CT5AX8 5 42 108 99
	2,4 mm		CT5BX5 5 42 115 99	CT5BX6 5 42 116 99	CT5BX7 5 42 117 99	CT5BX8 5 42 118 99
	3,2 mm		CT5CX5 5 42 125 99	CT5CX6 5 42 126 99	CT5CX7 5 42 127 99	CT5CX8 5 42 128 99
	5,0 mm		CT5DX5 5 42 135 99	CT5DX6 5 42 136 99	CT5DX7 5 42 137 99	CT5DX8 5 42 138 99
For 100 W soldering iron (W101)						
Chisel tip straight 	3,2 mm		-	CT6C6 5 42 206 99	CT6C7 5 42 207 99	CT6C8 5 42 208 99
	5,0 mm		-	CT6D6 5 42 216 99	CT6D7 5 42 217 99	CT6D8 5 42 218 99
	7,0 mm		-	CT6E6 5 42 226 99	CT6E7 ① 5 42 227 99	CT6E8 5 42 228 99
			-			
Chisel tip bent (45°) 	3,2 mm		-	CT6CX6 5 42 306 99	CT6CX7 5 42 307 99	CT6CX8 5 42 308 99
	5,0 mm		-	CT6DX6 5 42 316 99	CT6DX7 5 42 317 99	CT6DX8 5 42 318 99
	7,0 mm		-	CT6EX6 5 42 326 99	CT6EX7 5 42 327 99	CT6EX8 5 42 328 99
			-			
For 200 W soldering iron (W201)						
Chisel tip straight 	7,0 mm		-	CT2E6 5 42 406 99	CT2E7 5 42 407 99	CT2E8 5 42 408 99
	10,0 mm		-	CT2F6 5 42 416 99	CT2F7 ① 5 42 417 99	CT2F8 5 42 418 99
	11,0 mm		-	CT2G6 5 42 426 99	CT2G7 5 42 427 99	CT2G8 5 42 428 99
			-			
Chisel tip bent 	7,0 mm		-	CT2EX6 5 42 506 99	CT2EX7 5 42 507 99	CT2EX8 5 42 508 99
	10,0 mm		-	CT2FX6 5 42 516 99	CT2FX7 5 42 517 99	CT2FX8 5 42 518 99
			-			

① Scope of delivery W61