



Switching schematics

Switching from the DC side (GS)



Half-wave rectifier

Example for switching from the DC side of motors with ?-connection. Motor: 3 x 400V AC Rectifier output: 180V DC coil voltage: 162-236V DC



Bridge rectifier

Example for switching from the DC side of motors with Y-connection. Motor: 3 x 400V AC

Rectifier input: Neutral point and phase 230V AC

Rectifier output: 207V DC Coil voltage: 162-236V DC